



# MAGNEHELIC® DIFFERENTIAL PRESSURE GAGES Indicate Positive, Negative or Differential, Accurate within 1%





Standard Magnehelic® gage



High Accuracy Magnehelic® gage Note: Shown with optional -SS bezel

WILL UNSEAT ITSELF WHEN GAGE [3] 6-32 X 3/16 [4.76] DEEP HOLES EQUALLY SPACED ON A Ø4-1/8 [104.78] BOLT CIRCLE IS OVERPRESSURIZED .025 [.64] SPACE CREATED BY 3 SPACER PADS WHEN SURFACE MOUNTED. FOR PANEL MOUNTING DO NOT OBSTRUCT. PROVIDES PATH FOR RELIEF OF OVERPRESSURE. 1/8 FEMALE NPT - [13.49] HIGH PRESSURE 1/8 FFMALE CONNECTION NPT HIGH **PRESSURE** 1-1/4 [31.75] CONNECTION [44.45] 1/8 FEMALE Ø4-1/2 NPT LOW [114.3] 1/2 PRESSURE [12.70] CONNECTION 014-3/4 15/32 [11.91] [120.65] 1/8 FEMALE NPT LOW 11/16 1-11/16 [42.86] 7/16 [11.11] PRESSURE CONNECTION [17.46] 17/32 [13.49] 94-3/4 [120.65] 1/8 FEMALE NPT PANEL CUTOUT 1-1/4 HIGH PRESSURE CONNECTION [31.75] 1-3/4 [44.45] a4-47/64 [120.27] [114.3] [12.70] 1/8 FEMALE ø5-1/2 11/16 NPT LOW [139 70] [11.91] [17.46]

RUBBER PRESSURE RELIEF PLUG

Select the Series 2000 Magnehelic® Differential Pressure Gages for a versatile low differential pressure gage with a wide choice of 81 models and 27 options to choose from. Using Dwyer's simple, frictionless Magnehelic® gage movement, it quickly indicates air or non-corrosive gas pressures--either positive, negative (vacuum) or differential. The design resists shock, vibration, over-pressures and is weatherproof

Select the -HA High Accuracy Magnehelic® gage option for an accuracy within 1% of full-scale. Also included with the -HA option at no extra cost are a mirrored scale overlay and a 6 point calibration certificate.

### FEATURES/BENEFITS

Differential Pressure Gages

- · Easy to read gage through undistorted plastic face permits viewing from far away
- · Patented design provides quick response to pressure changes means no delay in assessing critical situations
- Durable and rugged housing and high-quality components combine to provide longservice life and minimized down-time
- · High accuracy option is twice as accurate as the standard Magnehelic® gage

### **APPLICATIONS**

- · Filter monitoring
- · Air velocity with Dwyer pitot tube
- · Blower vacuum monitoring
- · Fan pressure indication
- · Duct, room or building pressures
- · Clean room positive pressure indication

ACCESSORIES					
Model	Description				
A-432	Portable kit; combine carrying case with any Magnehelic® gage of				
	standard range, except high pressure connection. Includes 9 ft (2.7				
	m) of 3/16" ID rubber tubing, standhang bracket and terminal tube with holder				
A-605	Air filter gage accessory kit; adapts any standard Magnehelic® gage				
	for use as an air filter gage. Includes aluminum surface mounting				
	bracket with screws, two 5 ft (1.5 m) lengths of 1/4" aluminum tubing,				
	two static pressure tips and two molded plastic vent valves, integral				
	compression fittings on both tips and valves				
A-605B	Air filter gage accessory kit; air filter kit with two plastic open/close				
	valves, two 4" steel static tips, plastic tubing and mounting flange				
A-605C	Air filter gage accessory kit; air filter kit with two plastic open/close				
	valves, two plastic static tips, plastic tubing and mounting flange				

#### **SPECIFICATIONS**

MOUNTING RING

Service: Air and non-combustible, compatible gases (natural gas option available). Note: May be used with hydrogen. Order a Buna-N diaphragm. Pressures must be less than 35 psi.

PRESSURE

CONNECTION

3/16

[4.76]

[64.29]

Wetted Materials: Consult factory.

Housing: Die cast aluminum case and bezel, with acrylic cover. Exterior finish is coated gray to withstand 168 hour salt spray corrosion test.

Accuracy: ±2% (-HA model ±1) of FS (±3% (-HA ±1.5%) on -0, -100PA, -125PA, -10MM and ±4% (-HA ±2%) on -00, -60PA, -6MM ranges), throughout range at 70°F (21.1°C)

Pressure Limits: -20 in Hg to 15 psig (-0.677 to 1.034 bar); MP option: 35 psig (2.41 bar); HP option: 80 psig (5.52 bar).

Enclosure Rating: IP67.

Overpressure: Relief plug opens at approximately 25 psig (1.72 bar), standard

gages only.

Temperature Limits: 20 to 140°F\* (-6.67 to 60°C). -20°F (-28°C) with low

temperature option.

Size: 4" (101.6 mm) diameter dial face.

Mounting Orientation: Diaphragm in vertical position. Consult factory for other position orientations.

Process Connections: 1/8" female NPT duplicate high and low pressure taps - one pair side and one pair back

Weight: 1 lb 2 oz (510 g), MP & HP 2 lb 2 oz (963 g).

Standard Accessories: Two 1/8" NPT plugs for duplicate pressure taps, two 1/8" pipe thread to rubber tubing adapter, and three flush mounting adapters with screws. (Mounting and snap ring retainer substituted for three adapters in MP & HP gage accessories.)

Agency Approvals: Meets the technical requirements of EU Directive 2011/65/EU (RoHS II). Note: -SP models not RoHS approved.

Note: For applications with high cycle rate within gage total pressure rating, next higher rating is recommended. See Medium and High pressure options

\*Low temperature models available as special options





A-432

A-605



# MAGNEHELIC® DIFFERENTIAL PRESSURE GAGES Indicate Positive, Negative or Differential, Accurate within 1%



Bezel provides flange for flush mounting in panel.

Clear plastic face is highly resistant to breakage. Provides undistorted viewing of pointer and scale.

Precision litho-printed scale is accurate and easy to read.

Calibrated range spring is flat spring steel. Small amplitude of motion assures consistency and long life. It reacts to pressure on diaphragm. Live length adjustable for calibration.

Red tipped pointer of heat treated aluminum tubing is easy to see. It is rigidly mounted on the helix shaft.


Pointer stops of molded rubber prevent pointer over-travel without damage

"Wishbone" assembly provides mounting for helix, helix bearings and pointer shaft.

Jeweled bearings are shock-resistant mounted; provide virtually friction-free motion for helix. Motion damped with high viscosity silicone fluid.

**Helix** is precision made from an alloy of high magnetic permeability. Mounted in jeweled bearings, it turns freely, following the magnetic field to move the pointer across the

Zero adjustment screw is conveniently located in the plastic cover, and is accessible without removing cover. O-ring seal provides pressure tightness.



O-ring seal for cover assures pressure integrity of case.

#### **OVERPRESSURE PROTECTION**

Blowout plug is comprised of a rubber plug on the rear which functions as a relief valve by unseating and venting the gage interior when over pressure reaches approximately 25 psig (1.7 bar). To provide a free path for pressure relief, there are four spacer pads which maintain 0.023" clearance when gage is surface mounted. Do not obstruct the gap

created by these pads.
The blowout plug is not used on models above 180" of water pressure, medium or high pressure models, or on gages which require an elastomer other than silicone for the

diaphragm.

The blowout plug should not be used as a system overpressure control. High supply pressures may still cause the gage to fail due to over pressurization, resulting in property damage or serious injury. Good engineering practices should be utilized to prevent your system from exceeding the ratings of any component.

**Die cast aluminum case** is precision made and iridite-dipped to withstand 168 hour salt spray corrosion test. Exterior finished in baked dark gray hammerloid. One case size is used for all standard pressure options, and for both surface and flush mounting.

Silicone rubber diaphragm with integrally molded O-ring is supported by front and rear plates. It is locked and sealed in position with a sealing plate and retaining ring. Diaphragm motion is restricted to prevent damage due to overpressures.

Samarium Cobalt magnet mounted at one end of range spring rotates helix without mechanical linkages.

	Range,		Range,		Range, MM		Range,		Dual Scale Air	Velocity Units
		Model	PSI	Model	of Water	Model	kPa		For use with pi	
			0-1		0-6		0-0.5		li oi doc witii pi	tot tabo
			0-2		0-10		0-1			
	050	2203	0-3			2000-1.5KPA				Range, in w.c./
			0-4				0-2			Velocity F.P.M.
	0-2.0		0-5		0-30		0-2.5		2000-00AV†••	
			0-10	2000-50MM			0-3			300-2000
			0-15				0-4			050/
	0-5.0		0-20				0-5			500-2800
			0-30				0-8			0-1.0/
	0-8.0						0-10			500-4000
	0-10		Range, CM		0-200		0-15			0-2.0/
2012	0-12	Model	of Water	2000-250MM			0-20			1000-5600
2015	0-15				0-300	2000-25KPA	0-25			0-5.0/
2020			0-15	Zero Center Ra		2000-30KPA	0-30			2000-8800
			0-20		3-0-3	1				0-10/
2030	0-30		0-25		5-0-5	Zero Center F				2000-12500
	0-40		0-50		10-0-10	2300-1KPA	.5-05			2000 12000
2050			0-80			2300-2KPA	1-0-1			
		2000-100CM		2000-60NPA†**	40.0.50	2300-2.5KPA				
	0-80	2000-150CM			0-30		1.5-0-1.5			
		2000-200CM			0-60	Dual Scale Er				
	0-120	2000-250CM			0-100		Range,	Range,	,	
2150	0-150	2000-300CM			0 125			Pa or k		
		Zero Center I		2000-1201A	0.250		025	0-62 Pa	a	
	0-180	2300-4CM	2-0-2		N-300			0-125 F		
2250*	0-250	2300-10CM	5-0-5		0-500			0-250 F		
		2300-30CM	15-0-15		0.750	2002D	0-2.0	0-500 F	<sup>2</sup> a	
Zero Center	Ranges				0-1000	2003D	0-3.0	0-750 F		
	0.125-0-0.125	i		Zero Center Ra		2004D		0-1.0 kl		
	25-025					2005D	0-5.0	0-1.25	kPa	
	5-05							0-1.5 kl		
	1-0-1				30-0-30			0-2.0 kl		
	2-0-2						0-10	0-2.5 kl		
	5-0-5							0-3.7 kl		
	10-0-10			2300-200PA 2300-250PA				0-5 kPa		
	15-0-15							0-6.2 kl		
								0-12.4		
				2300-500PA 2300-1000PA	250-0-250	2060D	0-60	0-15 kF	<sup>2</sup> a	

**VELOCITY AND VOLUMETRIC FLOW UNITS** Scales are available on the Magnehelice gage that read in velocity units (FPM, m/s) or volumetric flow units (SCFM, m³/s, m³/h). Stocked velocity units with dual range scales in inches w.c. and feet per minute are shown above. For other ranges contact the factory. When ordering volumetric flow scales please specify the maximum flow rate and its corresponding pressure.

Example: 0.5 in w.c. = 16,000 CFM.

ACCES	ACCESSORIES					
Model	Description					
	Safety relief valve 3-piece magnet kit for mounting Magnehelic® gage directly to magnetic surface Rubber gasket for panel mounting Plastic carry case 3-way vent valves. In applications where pressure is continuous and the Magnehelic® gage is connected by metal or plastic tubing which cannot be easily removed, we suggest using Dwyer A-310A vent valves to connect gage. Pressure can then be removed to check or re-zero the gage					









## HIGH ACCURACY MAGNEHELIC® DIFFERENTIAL PRESSURE GAGE





Twice as accurate as the standard Magnehelic® gage

Mirrored scale overlay eliminates parallax error

IP67 weatherproof housing

Optional brushed SS bezel



6-point calibration certificate included

OPTIONS - HIGH ACCURACY MAGNEHELIC® GAGE				
To order				
add suffix:	Description			
-HA	High accuracy Magnehelic® gage. Accuracy			
	within 1% and weatherproof. Also includes			
	mirrored scale overlay and a six point			
	calibration certificate			
-SS	Corrosion resistant brushed 304 stainless			
	steel bezel			

Accuracy Specifications: See page 20 (Series 2000)

## **DITIONAL GAGE OPTIONS**








OPTIONS - OTHER OPTIONAL BEZELS				
To order add suffix:	Description			
-CB	Chrome bezel option: A chrome plated aluminum bezel for an			
	aesthetically pleasing finish when mounting on metal surfaces			
	such as control panels.			
-SB	Stainless steel bezel option: 304 stainless steel electro polished			
	Ra 16 finished bezel.			
-SS	Corrosion resistant brushed 304 stainless steel bezel			







Adjustable signal flag



Transparent overlay



Mirrored scale overlay



Integrated mounting plate


-СВ	Chrome bezel option: A chrome plated aluminum bezel for an aesthetically pleasing finish when mounting on metal surfaces				
	such as control panels.				
-SB	Stainless steel bezel option: 304 stainless steel electro polished				
	Ra 16 finished bezel.				
-SS	Corrosion resistant brushed 304 stainless steel bezel				
OPTIONS - LED SET POINT INDICATOR					
To order add suffix:	Description				
-SP	Bright red LED on right scale shows when set point is reached.				
	Field adjustable from gage face, unit operates on 12-24				
	VDC Cot point indicator entire composition medium procesure				

-SP	Bright red LED on right scale shows when set point is reached.			
	Field adjustable from gage face, unit operates on 12-24			
	VDC. Set point indicator option comes with medium pressure			
	(MP) bezel.			
Note: 4-13/16" hole for	or flush mounting.			
<b>OPTIONS - ADJUSTA</b>	ABLE SIGNAL FLAG			
To order add suffix:	Description			
-ASF	Integral with plastic gage cover. Available for most models			
	except those with medium or high pressure construction. Can be			
	ordered with gage or separate.			
OPTIONS - TRANSPARENT OVERLAYS				
To order add suffix:	Description			
-G	Green (to highlight and emphasize critical pressures)			
-R	Red (to highlight and emphasize critical pressures)			
-Y	Yellow (to highlight and emphasize critical pressures)			
OPTIONS - MIRRORED SCALE OVERLAY				
To order add suffix:	Description			
-M	A mirrored scale overlay is also available to assist in reducing			

	parallax error.			
OPTIONS - INTEGRATED MOUNTING PLATE				
To order add suffix:	Description			
-AHU1	Furnished with attached surface mounting plate			
-AHU2	Furnished with attached surface mounting plate and including			
	A-481 installer kit (2 plastic static pressure tips and 7'of			
	PVC tubing)			



OPTIONS - FOR HIGH STATE PRESSURE APPLICATIONS		
Description		
High pressure option: for pressures to 80 psig		
Medium pressure option: for pressures to 35 psig		








PVN ENGINEERING CO.,LTD. | Call : 02-911-4761 | Email : pvn@pvn.co.th



## MAGNEHELIC® GAGE MOUNTING ACCESSORIES



A single case size is used for most models of Magnehelic® gages. They can be flush or surface mounted with standard hardware supplied. Complete mounting and connection fittings plus instructions are furnished with each instrument. A 4-9/16" hole is required for flush panel mounting.

Flush mounting is easily accomplished with the new A-300 Flush Mounting bracket. This bracket provides a solution to quickly and conveniently flush mount the Magnehelic® gage. The A-300 is ideal for mounting the Magnehelic® gage on control panel doors.

The A-368 is a simple bracket for quickly surface mounting the Magnehelic® gage. After securing the Magnehelic® gage to the A-368 bracket, mount the bracket on any flat surface.

The A-369 allows the Magnehelic® gage to be easily carried to locations where pressure readings need to be taken. The A-369 can stand on its own or hang on a nail or hook.

ACCESSORIES				
Model	Description			
A-610	Pipe mounting kit for installing on 1-1/4" to 2" horizontal or vertical pipe			
A-286	Magnehelic® gage panel mounting flange			
A-369	Stand-hang bracket, aluminum, for Magnehelic® gage			
A-300	Flush mounting bracket			
A-464	Flush mount kit for Magnehelic® gage			
A-368	Surface mounting plate, aluminum, for Magnehelic® gage			
A-299	Mounting bracket, flush mount for Magnehelic® gage, bracket is then			
	surface mounted, steel with gray hammerloid epoxy finish			
A-371	Surface mounting bracket, use with medium pressure (-MP) or high			
	pressure (-HP) models only			